

AlephObjects.com

3D Printers, Parts, and Plastics

+1-970-377-1111

shop@alephobjects.com

626 West 66th Street

Loveland, Colorado 80538



Service Bulletin

| | |
|---------------------------------|---|
| Affected product: | TAZ 3D printers, versions 4.1 and below |
| Effective date: | October 13 2014 |
| Serial numbers affected: | KT-PR0010-5001 through KT-PR0016-7XXX |
| Service issue: | When printing a tall object, the extruder wiring harness can potentially be caught on the printed model, leading to print failure. The installation of an additional zip-tie can minimize the risk of this occurring. |

Indication:

Some users have reported that when printing a tall object the extruder harness can be caught on the model, leading to print failures.

Corrective Action:

Install an additional zip-tie onto the top-rear aluminum extrusion, approximately 200mm away from the original zip-tie holding the extruder harness. Installation of the additional zip-tie in the middle of the top-rear extrusion does not need to be exact. Verify full axis travel range prior to installing the zip-tie.

